



20MHz_High_16QAM_1@99



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 20:55:28


20MHz_High_16QAM_27@73



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 20:57:37


Band 66, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 21:00:33

1.4MHz_Low_QPSK_6@0




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 21:01:42

1.4MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 21:02:53

1.4MHz_Low_16QAM_6@0




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 21:04:03

1.4MHz_High_QPSK_1@5




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:05:18

1.4MHz_High_QPSK_6@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:06:33

1.4MHz_High_16QAM_1@5




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:07:49

1.4MHz_High_16QAM_6@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:09:04

3MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:11:00

3MHz_Low_QPSK_15@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:11:44

3MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:12:29

3MHz_Low_16QAM_15@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:13:14

3MHz_High_QPSK_1@14




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:14:03

3MHz_High_QPSK_15@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:14:53

3MHz_High_16QAM_1@14




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:15:43

3MHz_High_16QAM_15@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:16:32

5MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:17:15

5MHz_Low_QPSK_25@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:17:58

5MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:18:39

5MHz_Low_16QAM_25@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:19:20

5MHz_High_QPSK_1@24




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:19:56

5MHz_High_QPSK_25@0




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:20:32

5MHz_High_16QAM_1@24




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:21:08

5MHz_High_16QAM_25@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:21:44

10MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:23:13

10MHz_Low_QPSK_50@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:23:59

10MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:24:44

10MHz_Low_16QAM_27@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:25:31

10MHz_High_QPSK_1@49




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:26:12

10MHz_High_QPSK_50@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:26:54

10MHz_High_16QAM_1@49




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:27:35

10MHz_High_16QAM_27@23




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:28:16

15MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:29:12

15MHz_Low_QPSK_75@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:30:05

15MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:30:58

15MHz_Low_16QAM_27@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:31:52

15MHz_High_QPSK_1@74




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:32:43

15MHz_High_QPSK_75@0




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:33:34

15MHz_High_16QAM_1@74




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:34:24

15MHz_High_16QAM_27@48




ProjectNo.: 2507T32510E-RF Tester: Brcaylon Ma
Date: 13.OCT.2025 21:35:14

20MHz_Low_QPSK_1@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:37:24

20MHz_Low_QPSK_100@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:38:29

20MHz_Low_16QAM_1@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:39:33

20MHz_Low_16QAM_27@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:40:39

20MHz_High_QPSK_1@99




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:41:44

20MHz_High_QPSK_100@0




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:42:49

20MHz_High_16QAM_1@99



ProjectNo.:2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:43:54

20MHz_High_16QAM_27@73



ProjectNo.:2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 21:44:59

Spurious Emissions at Antenna Terminal

FCC Part 22H


Band 5, Normal

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)	-32.70	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)	-32.77	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)	-31.84	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~9.49GHz)	-32.97	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)	-32.47	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~9.49GHz)	-32.88	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~9.49GHz)	-32.82	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)	-31.83	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~9.49GHz)	-33.07	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~9.49GHz)	-33.18	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)	-32.82	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~9.49GHz)	-33.22	See Graphs	Pass

Note:1RB was the worst case.


Band 5, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:58:55

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:59:37

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 23:00:12

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 23:01:47

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 23:02:21

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 23:02:55

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:04:29

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:05:04

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:05:38

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:07:13

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:08:22

10MHz_High_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 23:09:31


FCC Part 24E**Band 2, Normal**

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.98	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-31.27	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)	-31.27	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.76	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-30.15	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~20.1GHz)	-30.51	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.13	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-30.75	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~20.1GHz)	-30.60	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.59	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-29.84	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~20.1GHz)	-29.13	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.99	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-31.14	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~20.1GHz)	-30.84	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~20.1GHz)	-30.56	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)	-30.64	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~20.1GHz)	-30.73	See Graphs	Pass


Note:1RB was the worst case.

Band 2, Normal**1RB was the worst case**


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:10:28


1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:11:09


1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:11:52


3MHz_Low_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:13:45


3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)

ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:14:26

3MHz_High_QPSK_1@0(30MHz~20.1GHz)


ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 22:15:07

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:16:57

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:17:39

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:18:21

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:20:08

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:21:33

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:22:57

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:24:51

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:26:16

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:27:40

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:30:08

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:31:32

20MHz_High_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.: 2507T32510E-RF Tester: Baylon Ma
Date: 13.OCT.2025 22:32:56

FCC Part 27

Band 4, Normal

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-31.37	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-30.47	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)	-31.12	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-31.45	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-30.90	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~18.55GHz)	-29.63	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-30.42	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-31.50	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~18.55GHz)	-30.98	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-30.66	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-30.89	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~18.55GHz)	-30.88	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-29.93	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-30.70	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~18.55GHz)	-31.44	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~18.55GHz)	-31.15	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)	-30.49	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~18.55GHz)	-29.81	See Graphs	Pass

Band 7, Normal

Mode	Value (dBm)	Limit	Verdict
5MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-36.32	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-36.49	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~26.7GHz)	-36.38	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-35.47	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-36.11	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~26.7GHz)	-36.69	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-36.98	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-36.07	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~26.7GHz)	-36.00	See Graphs	Pass

Mode	Value (dBm)	Limit	Verdict
20MHz_Low_QPSK_1@0(30MHz~26.7GHz)	-36.25	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)	-36.68	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~26.7GHz)	-36.31	See Graphs	Pass


Band 66, Normal

Mode	Value (dBm)	Limit	Verdict
1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-30.96	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-30.68	See Graphs	Pass
1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)	-30.96	See Graphs	Pass
3MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-31.23	See Graphs	Pass
3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-30.23	See Graphs	Pass
3MHz_High_QPSK_1@0(30MHz~18.8GHz)	-30.21	See Graphs	Pass
5MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-31.18	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-30.11	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~18.8GHz)	-29.39	See Graphs	Pass
10MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-30.66	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-31.29	See Graphs	Pass
10MHz_High_QPSK_1@0(30MHz~18.8GHz)	-30.83	See Graphs	Pass
15MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-30.72	See Graphs	Pass
15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-30.60	See Graphs	Pass
15MHz_High_QPSK_1@0(30MHz~18.8GHz)	-31.03	See Graphs	Pass
20MHz_Low_QPSK_1@0(30MHz~18.8GHz)	-30.70	See Graphs	Pass
20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)	-30.40	See Graphs	Pass
20MHz_High_QPSK_1@0(30MHz~18.8GHz)	-31.10	See Graphs	Pass

Note:1RB was the worst case.


Band 4, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:34:52

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:35:32

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:36:13

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:37:56

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:38:37

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Testers: Baylon Ma
Date: 13.OCT.2025 22:39:17

5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:40:58

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:41:39

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:42:20

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:44:01

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:45:24

10MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:46:47