



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:49:11

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:50:34

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:51:57

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:54:18

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:55:41


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507T32510E-RF Tester:Braylon Ma
Date: 13.OCT.2025 22:57:03


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:47:00

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:47:41

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:48:22

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:49:58

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:51:22

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 21:52:50

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:55:27

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:56:58

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 21:58:30

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:01:06

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:02:37


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 22:04:10


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:11:20

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:12:01

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:12:43

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:13:26

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:14:07

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Testers: Bwaylon Ma
Date: 13.OCT.2025 23:14:48

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:15:31

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:16:12

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:16:53

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:18:41

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:20:04

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Braylon Ma
Date: 13.OCT.2025 23:21:26

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:22:52

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:24:15

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:25:38

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:27:59

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:29:22

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507T32510E-RF Tester: Breydon Ma
Date: 13.OCT.2025 23:30:45