










Band4_1.4MHz_QPSK_20175_1RB#0_3000~20000_3000~20000




Band4_1.4MHz_16QAM_20175_1RB#0_0.009~0.15_0.009~0.15








Band4_1.4MHz_16QAM_20175_1RB#0_1000~3000_1000~3000




Band4_1.4MHz_16QAM_20175_1RB#0_3000~20000_3000~20000







Band4_1.4MHz_QPSK_20393_1RB#0_0.009~0.15_0.009~0.15




Band4_1.4MHz_QPSK_20393_1RB#0_0.15~30_0.15~30









Band4_1.4MHz_QPSK_20393_1RB#0_3000~20000_3000~20000





Band4_1.4MHz_16QAM_20393_1RB#0_0.009~0.15_0.009~0.15























Band4_3MHz_16QAM_19965_1RB#0_1000~3000_1000~3000




Band4_3MHz_16QAM_19965_1RB#0_3000~20000_3000~20000












Band4_3MHz_QPSK_20175_1RB#0_3000~20000_3000~20000




Band4_3MHz_16QAM_20175_1RB#0_0.009~0.15_0.009~0.15








Band4_3MHz_16QAM_20175_1RB#0_1000~3000_1000~3000




Band4_3MHz_16QAM_20175_1RB#0_3000~20000_3000~20000







Band4_3MHz_QPSK_20385_1RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_QPSK_20385_1RB#0_0.15~30_0.15~30









Band4_3MHz_QPSK_20385_1RB#0_3000~20000_3000~20000





Band4_3MHz_16QAM_20385_1RB#0_0.009~0.15_0.009~0.15

















Band4_5MHz_QPSK_19975_1RB#0_3000~20000_3000~20000





Band4_5MHz_16QAM_19975_1RB#0_0.009~0.15_0.009~0.15













Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity









Band4_5MHz_16QAM_20175_1RB#0_1000~3000_1000~3000





Band4_5MHz_16QAM_20175_1RB#0_3000~20000_3000~20000
















Band4_5MHz_16QAM_20375_1RB#0_1000~3000_1000~3000




Band4_5MHz_16QAM_20375_1RB#0_3000~20000_3000~20000







Band4_10MHz_QPSK_20000_1RB#0_0.009~0.15_0.009~0.15




Band4_10MHz_QPSK_20000_1RB#0_0.15~30_0.15~30







Band4_10MHz_QPSK_20000_1RB#0_3000~20000_3000~20000



Band4_10MHz_16QAM_20000_1RB#0_0.009~0.15_0.009~0.15



