






Band2-1.4MHz-16QAM-19193-1RB#0-Range1:30~1000MHz




Band2-1.4MHz-16QAM-19193-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:40:35

Band2-1.4MHz-16QAM-19193-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:29:07

Band2-3MHz-QPSK-18615-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:29:16

Band2-3MHz-QPSK-18615-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:29:24


Band2-3MHz-QPSK-18615-1RB#0-Range3:2000~20000MHz




Band2-3MHz-QPSK-18900-1RB#0-Range1:30~1000MHz




Band2-3MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz



Band2-3MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




Band2-3MHz-QPSK-19185-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:30:18

Band2-3MHz-QPSK-19185-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:30:27


Band2-3MHz-QPSK-19185-1RB#0-Range3:2000~20000MHz




Band2-3MHz-16QAM-18615-1RB#0-Range1:30~1000MHz




Band2-3MHz-16QAM-18615-1RB#0-Range2:1000~2000MHz




Band2-3MHz-16QAM-18615-1RB#0-Range3:2000~20000MHz




Band2-3MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-3MHz-16QAM-18900-1RB#0-Range2:1000~2000MHz




Band2-3MHz-16QAM-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:42:20

Band2-3MHz-16QAM-19185-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:42:29

Band2-3MHz-16QAM-19185-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:42:38

Band2-3MHz-16QAM-19185-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:31:14

Band2-5MHz-QPSK-18625-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:31:23

Band2-5MHz-QPSK-18625-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:31:31


Band2-5MHz-QPSK-18625-1RB#0-Range3:2000~20000MHz



Band2-5MHz-QPSK-18900-1RB#0-Range1:30~1000MHz




Band2-5MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:32:22

Band2-5MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:32:17


Band2-5MHz-QPSK-19175-1RB#0-Range1:30~1000MHz



Band2-5MHz-QPSK-19175-1RB#0-Range2:1000~2000MHz




Band2-5MHz-QPSK-19175-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:43:21

Band2-5MHz-16QAM-18625-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:43:30

Band2-5MHz-16QAM-18625-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:43:38

Band2-5MHz-16QAM-18625-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:43:52


Band2-5MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-5MHz-16QAM-18900-1RB#0-Range2:1000~2000MHz




Band2-5MHz-16QAM-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:44:24

Band2-5MHz-16QAM-19175-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:44:32

Band2-5MHz-16QAM-19175-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:44:11

Band2-5MHz-16QAM-19175-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:33:19

Band2-10MHz-QPSK-18650-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:33:28

Band2-10MHz-QPSK-18650-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:33:36


Band2-10MHz-QPSK-18650-1RB#0-Range3:2000~20000MHz



Band2-10MHz-QPSK-18900-1RB#0-Range1:30~1000MHz




Band2-10MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:34:27

Band2-10MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:34:22

Band2-10MHz-QPSK-19150-1RB#0-Range1:30~1000MHz




Date: 19 APR 2025 09:34:30

Band2-10MHz-QPSK-19150-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:34:39


Band2-10MHz-QPSK-19150-1RB#0-Range3:2000~20000MHz




Band2-10MHz-16QAM-18650-1RB#0-Range1:30~1000MHz




Band2-10MHz-16QAM-18650-1RB#0-Range2:1000~2000MHz




Band2-10MHz-16QAM-18650-1RB#0-Range3:2000~20000MHz




Band2-10MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-10MHz-16QAM-18900-1RB#0-Range2:1000~2000MHz




Band2-10MHz-16QAM-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:46:29

Band2-10MHz-16QAM-19150-1RB#0-Range1:30~1000MHz



Date: 19 APR 2025 09:46:38


Band2-10MHz-16QAM-19150-1RB#0-Range2:1000~2000MHz



The screenshot shows a Spectrum Analyzer interface. At the top, the title is "Spectrum". Below it, the settings are: Ref Level 25.00 dBm, Att 35 dB, RBW 1 MHz, SWT 1 ms, VBW 3 MHz, Mode Auto Sweep, and Count 50/50 TDF. The main display area shows a spectrum plot with a noise floor around -30 dBm. A red horizontal line is drawn at -13.000 dBm, labeled "D1 -13.000 dBm". A blue peak is labeled "M1[1]" with a value of -28.77 dBm and a frequency of 951.020 MHz. The x-axis is labeled "Start 30.0 MHz" and "1000 pts". The y-axis is labeled "Stop 1.0 GHz".


Date: 19 APR 2025 09:35:23

Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com Complaint call:0755-33681700 Complaint E-mail:complaint@cti-cert.com




Date: 19 APR 2025 09:35:32

Band2-15MHz-QPSK-18675-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:35:40


Band2-15MHz-QPSK-18675-1RB#0-Range3:2000~20000MHz



Band2-15MHz-QPSK-18900-1RB#0-Range1:30~1000MHz




Band2-15MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz




Date: 19 APR 2025 09:36:11

Band2-15MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




Date: 19 APR 2025 09:36:26

Band2-15MHz-QPSK-19125-1RB#0-Range1:30~1000MHz



Date: 19 APR 2025 09:36:34

Band2-15MHz-QPSK-19125-1RB#0-Range2:1000~2000MHz



Date: 19 APR 2025 09:36:43

Band2-15MHz-QPSK-19125-1RB#0-Range3:2000~20000MHz