

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = CN	Made in China
XX = MY	Assembled in China with PCBA from Malaysia
XX = MX	Assembled in Mexico



SEE Tabulation column
PART NUMBER "A"

SEE Tabulation column
COUNTRY OF ORIGIN "B"

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = MY	Assembled in China with PCBA from Malaysia

©2025 Kidde.


Wi-Fi


ETL
LISTED
US

CONFORMS TO:
UL STD 217
UL STD 2034
Multi-Criteria Smoke
and CO Alarm

PIN: L-000685-MY-00 RevA

Intertek
4002588

Smoke sensitivity: 3.10 +/- 0.89 %/ft OBS

Model RGCUDR-RW
Combination Photoelectric
Smoke/CO Alarm w/ Voice,
Wire-Free Interconnect, & Wi-Fi,
AA battery powered. Constant
exposures to high or low
temperatures or high humidity may
reduce battery life.


XXXXX


DSN: XXXXXXXXXXXXXXXXX

SMOKE ALARM: 3 long beeps,
repeating. **CO ALARM:** 4 quick beeps,
repeating. **STANDBY:** Green LED blinks
every 60s. **LOW**
BATTERY: Amber
LED blinks every 6s
with 1 chirp every 60s.
FAULT: Amber LED
blinks 1-4 times with 3
chirps every 60s. **END OF**
UNIT LIFE: Amber LED blinks
twice with 2 chirps every 60s. **Temp Range:** 40 °F (4.4 °C) to 100 °F (37.8 °C). **Humidity Range:**
10 to 95% relative humidity (RH), non-condensing. Clean annually. See User Guide for more info.

**WARNING:** Carbon monoxide (CO) is a colorless, odorless, poisonous gas.
You can't taste, see, or smell CO, but it can kill in just minutes. This alarm will sound in a 4-beep
pattern if life threatening levels of CO are detected. If the alarm sounds: 1) Immediately evacuate all occupants from the
space and go outdoors to fresh air. 2) Call emergency responders (911 or fire department) for help; notify the building or
vehicle owner, as necessary.

REPLACE BATTERIES AT LEAST ONCE A YEAR.

**WARNING:** USE ONLY BATTERIES SPECIFIED IN MARKING (Energizer E91, Gold
Peak 15A, Golden Power GLR6A). USE OF A DIFFERENT BATTERY MAY HAVE A DETRIMENTAL
EFFECT ON ALARM OPERATION. NOTE: Do not use lithium batteries in this unit. Unit will not
attach to mounting bracket without batteries installed.

Contains FCC ID SAK-ESP32S3 FCC ID 2BQ4X-RGCUDR-RW
Kidde, 1016 Corporate Park Drive, Mebane, NC 27302 1-877-542-5471
Assembled in China
with PCBA from Malaysia

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = MX	Assembled in Mexico

©2025 Kidde.


Wi-Fi


US

CONFORMS TO
UL STD 217
UL STD 2034
Multi-Criteria Smoke
and CO Alarm

PIN: L-000685-MX-00 RevA

Intertek
5032230

Smoke sensitivity: 3.10 +/- 0.89 %/ft OBS

Model RGCUDR-RW
Combination Photoelectric
Smoke/CO Alarm w/ Voice,
Wire-Free Interconnect, & Wi-Fi,
AA battery powered. Constant
exposures to high or low
temperatures or high humidity may
reduce battery life.


XXXXX


DSN: XXXXXXXXXXXXXXXXX

SMOKE ALARM: 3 long beeps,
repeating. **CO ALARM:** 4 quick beeps,
repeating. **STANDBY:** Green LED blinks
every 60s. **LOW**
BATTERY: Amber
LED blinks every 6s
with 1 chirp every 60s.
FAULT: Amber LED
blinks 1-4 times with 3
chirps every 60s. **END OF**
UNIT LIFE: Amber LED blinks
twice with 2 chirps every 60s. **Temp Range:** 40 °F (4.4 °C) to 100 °F (37.8 °C). **Humidity Range:**
10 to 95% relative humidity (RH), non-condensing. Clean annually. See User Guide for more info.

**WARNING:** Carbon monoxide (CO) is a colorless, odorless, poisonous gas.
You can't taste, see, or smell CO, but it can kill in just minutes. This alarm will sound in a 4-beep
pattern if life threatening levels of CO are detected. If the alarm sounds: 1) Immediately evacuate all occupants from the
space and go outdoors to fresh air. 2) Call emergency responders (911 or fire department) for help; notify the building or
vehicle owner, as necessary.

REPLACE BATTERIES AT LEAST ONCE A YEAR.

**WARNING:** USE ONLY BATTERIES SPECIFIED IN MARKING (Energizer E91, Gold
Peak 15A, Golden Power GLR6A). USE OF A DIFFERENT BATTERY MAY HAVE A DETRIMENTAL
EFFECT ON ALARM OPERATION. NOTE: Do not use lithium batteries in this unit. Unit will not
attach to mounting bracket without batteries installed.

Contains FCC ID SAK-ESP32S3 FCC ID 2BQ4X-RGCUDR-RW
Kidde, 1016 Corporate Park Drive, Mebane, NC 27302 1-877-542-5471
Assembled in Mexico

