




Internal Photos for SET OPTIMIZER

SO Sensor





SO Shaft

Photo from the side (After attaching of the strain gauge)



Photo from the side (half removed adhesive tape)



Photo from bottom (After attaching of the strain gauge and connecting to base terminal)




Photo from bottom (half removed adhesive tape)



Photo from bottom (After connecting only the lead wire to the base terminal)



Photo from upper



※ Then we attach the bottom case and fasten them with screws.