

Registration number: W6M22504-24342-FCC

FCC ID: 2BQNPSMARTCOLLARSTM


Set Up Photo of Radiated Emission

B032-23-1003


Below 1GHz




Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM





Above 1GHz






Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM






Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM
B032-23-1001






Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM





B032-23-1002





Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM





Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6M22504-24342-FCC

FCC ID: 2BQNPSMARTCOLLARSTM

Set Up Photo of Conducted Emission

B032-23-1003






Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM
B032-23-1001





Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M22504-24342-FCC
FCC ID: 2BQNPSMARTCOLLARSTM
B032-23-1002

