



COPAN GLOBAL CO.,LTD

121-12, Dosim-gil, Wabu-eup, Namyangju-si, Gyeonggi-do, Republic of Korea

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046
USA

Date: 10-21-2025

Ref: Reason for failure to attach label to exterior surface

FCC ID: 2BQUK-KPOPDEMONSAJA

This product is in the form of a light stick, and the design and appearance completeness of the product are the main competitive factors of the product.

As a result, attaching an authentication label to the outside may damage the design and reduce consumer awareness, making it difficult to attach it to the outside.

In addition, due to the structure of the battery box, the attachable plane is narrow or curved, so internal attachment is inevitable due to the high possibility of damage to and dropping the label.

Accordingly, the certification label was attached inside the product,

Consumers can clearly check the same authentication information through the product packaging box and manual.

Sincerely,

A handwritten signature in black ink, appearing to read 'SUN BIN LEE'.

SUN BIN LEE / Project Leader