



Annex B


Internal photos

Report No.: HK2506183192-E

Page 1 of 3







Antenna

