



TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTI250819014-0102E4



TEST REPORT

Report No.: MTi250819014-0102E4



TEST REPORT

Report No.: MTi250819014-0102E4

Appendix B: Duty Cycle


Test Result

Test Mode	Antenna	Frequency [MHz]	Transmission Duration [ms]	Transmission Period [ms]	Duty Cycle [%]
11A	Ant1	5180	2.03	3.05	66.56
		5200	2.03	3.06	66.34
		5240	2.03	3.06	66.34
		5745	2.03	3.06	66.34
		5785	2.04	3.06	66.67
		5825	2.03	3.05	66.56
11N20SISO	Ant1	5180	1.89	2.91	64.95
		5200	1.89	2.92	64.73
		5240	1.89	2.92	64.73
		5745	1.89	2.91	64.95
		5785	1.89	2.92	64.73
		5825	1.89	2.91	64.95
11N40SISO	Ant1	5190	0.93	1.96	47.45
		5230	0.93	1.96	47.45
		5755	0.93	1.96	47.45
		5795	0.93	1.96	47.45
11AC20SISO	Ant1	5180	1.90	3.21	59.19
		5200	1.90	2.93	64.85
		5240	1.90	2.92	65.07
		5745	1.90	2.92	65.07
		5785	1.90	2.93	64.85
		5825	1.90	2.93	64.85
11AC40SISO	Ant1	5190	0.94	1.96	47.96
		5230	0.94	1.96	47.96
		5755	0.93	1.96	47.45
		5795	0.93	1.96	47.45
11AX20SISO	Ant1	5180	1.46	2.49	58.63
		5200	1.46	2.49	58.63
		5240	1.46	2.49	58.63
		5745	1.46	2.49	58.63
		5785	1.46	2.49	58.63
		5825	1.46	2.48	58.87
11AX40SISO	Ant1	5190	0.76	1.78	42.70
		5230	0.77	1.79	43.02
		5755	0.77	1.80	42.78
		5795	0.76	1.79	42.46

TEST REPORT


Report No.: MTi250819014-0102E4

Test Graphs




TEST REPORT


Report No.: MTi250819014-0102E4



TEST REPORT


Report No.: MTI250819014-0102E4






TEST REPORT

Report No.: MTI250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4




TEST REPORT

Report No.: MTI250819014-0102E4




TEST REPORT

Report No.: MTi250819014-0102E4



TEST REPORT

Report No.: MTi250819014-0102E4



TEST REPORT

Report No.: MTI250819014-0102E4

