

Bird Buddy Inc.
169 Madison Ave STE 15233, New York NY United States 10016
Tel: 7372964618 ; Fax: 7472342628

Date: July 15, 2026

FCC Laboratory
7435 Oakland Mills Rd
Columbia MD 2104

SUBJECT: Class II Permissive Change for FCC ID: 2BSOW-BWS3004BAB, approval date: 12/04/2025

This is to request a Class II Permissive Change application for above referenced device. The changes filed under this application are:

1. Software changes: Disable speaker, reduce default video bitrate, reduce video buffer, disable Neural Network function.
2. Disable WLAN 5GHz band operation via embedded software.
3. Hardware changes are:

	Original model	Variant model
CPU	RTL-8735BDM-AA4-CG (WIFI a/b/g/n; DDR2 128MB)	RTL-8735BM-AA3-CG (WIFI b/g/n; DDR2 64MB)
Shielding cover on CPU	Yes	No
Speaker and audio driver	Yes	No
Connect type of Bird house	Magnetic	Pogo pin
No. of Solar panel	2	1

Except the change described above, the design, hardware, and software are exactly the same with original. Software security remains unchanged from the original application.

Sincerely,



Michael Dietz
michael.dietz@mybirdbuddy.com