





Date: 16.APR.2026 17:56:24


11AC20SISO_Ant1_5825_30~5650



11AC20SISO_Ant1_5825_5925~40000



11AC20SISO_Ant1_5825_27000~40000



Date: 16.APR.2026 17:56:43


11AC40SISO_Ant1_5190_30~5140




11AC40SISO_Ant1_5190_5360~40000



11AC40SISO_Ant1_5190_27000~40000




11AC40SISO_Ant1_5230_30~5140




11AC40SISO_Ant1_5230_5360~40000




11AC40SISO_Ant1_5230_27000~40000




11AC40SISO_Ant1_5755_30~5650




11AC40SISO_Ant1_5755_5925~40000




11AC40SISO_Ant1_5755_27000~40000




11AC40SISO_Ant1_5795_30~5650



11AC40SISO_Ant1_5795_5925~40000




11AC40SISO_Ant1_5795_27000~40000




Date: 16.APR.2026 17:58:09


11AC80SISO_Ant1_5210_30~5140



11AC80SISO_Ant1_5210_5360~40000



11AC80SISO_Ant1_5210_27000~40000



Date: 16.APR.2026 17:58:43


11AC80SISO_Ant1_5775_30~5650




11AC80SISO_Ant1_5775_5925~40000



11AC80SISO_Ant1_5775_27000~40000




11AX20SISO_Ant1_5180_30~5140




11AX20SISO_Ant1_5180_5360~40000




11AX20SISO_Ant1_5180_27000~40000




11AX20SISO_Ant1_5220_30~5140




11AX20SISO_Ant1_5220_5360~40000




11AX20SISO_Ant1_5220_27000~40000




11AX20SISO_Ant1_5240_30~5140



11AX20SISO_Ant1_5240_5360~40000




11AX20SISO_Ant1_5240_27000~40000




Date: 16.APR.2026 18:00:16


11AX20SISO_Ant1_5745_30~5650



11AX20SISO_Ant1_5745_5925~40000




11AX20SISO_Ant1_5745_27000~40000



Date: 16.APR.2026 18:00:38


11AX20SISO_Ant1_5785_30~5650



11AX20SISO_Ant1_5785_5925~40000



11AX20SISO_Ant1_5785_27000~40000



11AX20SISO_Ant1_5825_30~5650

