



**RETLIF
TESTING
LABORATORIES**

Put Us To The Test sm

3131 Detwiler Road
Harleysville, PA 19438 USA

Tel: (215) 256-4133 • Fax: (215) 256-4130 • www.retlif.com

Distek, Inc.

Bathless Dissolution Tester

FCC ID: 2BUPX-Olera

Test Setup Photographs



45 YEARS OF TESTING EXCELLENCE

Corporate Headquarters:
795 Marconi Avenue
Ronkonkoma, NY 11779 USA
Tel: (631) 737-1500
Fax: (631) 737-1497

101 New Boston Road
Goffstown, NH 03045 USA
Tel: (603) 497-4600
Fax: (603) 497-5281

Test Photographs Conducted Emissions



Test Setup



EUT Configuration



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Fundamental



EUT Configuration



Parallel Antenna Polarization, Below 30 MHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Fundamental



Antenna Parallel to Ground, Below 30 MHz



Perpendicular Antenna Polarization, Below 30 MHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Harmonics and Spurious



EUT Configuration



Parallel Antenna Polarization, Below 30 MHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Harmonics and Spurious



Parallel to Ground, Antenna Polarization, Below 30 MHz



Perpendicular Antenna Polarization, Below 30 MHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Harmonics and Spurious



Horizontal Antenna Polarization, 30 MHz to 200 MHz



Vertical Antenna Polarization, 30 MHz to 200 MHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs
Field Strength of Harmonics and Spurious



Horizontal Antenna Polarization, 200 MHz to 1 GHz



Vertical Antenna Polarization, 200 MHz to 1 GHz



Retlif Testing Laboratories

Report No. R-4109P-4

Test Photographs Frequency Tolerance



Temperature Variation



Voltage Variation



Retlif Testing Laboratories

Report No. R-4109P-4