

Disable Bluetooth function

Date: 2026-08-17

Federal Communications Commission

7435 Oakland Mills Road Columbia MD 21046 USA

Industry Canada

Certification and Engineering Bureau

Building 94, 3701 Carling Ave, Nepean, ON K2K 2Y7, CANADA

FCC ID: 2BUWU-AW32R

IC: 35239-AW32R

FCC ID: 2BUWU-CW32R


IC: 35239-CW32R

To Whom It May Concern:

We, fünfeinhalb Funksysteme GmbH declare

- Bluetooth function of device Access Point (M/N: BlitzFunk AW32R, with FCC ID: 2BUWU-AW32R, IC: 35239-AW32R) that assembles three identical wireless module #1 (Model AMLGA7921), wireless module #2 (Model AMLGA7921) and wireless module #3 (Model AMLGA7921) is disabled by firmware.
- Bluetooth function of device Client (M/N: BlitzFunk CW32R, with FCC ID: 2BUWU-CW32R, IC: 35239-CW32R) tat assembles two identical wireless module #1 (Model AMLGA7921) and wireless module #2 (Model AMLGA7921) is disabled by firmware.

Sincerely yours,



Applicant Signature

Printed Name: Andreas Trassl

Title: Product Management

Address: Chemnitzer Straße 78A, 01187 Dresden, Germany

Tel.: +49 152 3482 5585

Email: andreas.trassl@fuenfeinhalb.de