

Hangzhou Haixun Information Technology Co., Ltd.
Room 1271, Building 7, Tianxingguojizhongxin, Fengtan Road No. 508, Xiangfu
Street, Gongshu, Hangzhou, Zhejiang, 310011, China

Apr. 16, 2026

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID: 2BVC5-HAIXUN

Models: HX-X9-L, HX-X9-R, HX-U7-L, HX-U7-R, NL-YKE8-L, NL-YKE8-R, NL-YKV5-L, NL-YKV5-R, NL-YKS6-L, NL-YKS6-R, WLJ-Y90L, WLJ-Y90R, XCQQ-X60L, XCQQ-X60R

To Whom It May Concern:

We, The Hangzhou Haixun Information Technology Co., Ltd. hereby declare that the model : HX-X9-L is identical with the model : HX-X9-R, HX-U7-L, HX-U7-R, NL-YKE8-L, NL-YKE8-R, NL-YKV5-L, NL-YKV5-R, NL-YKS6-L, NL-YKS6-R, WLJ-Y90L, WLJ-Y90R, XCQQ-X60L, XCQQ-X60R
, except the model name.

Sincerely,

Hangzhou Haixun Information Technology Co., Ltd.
Signature:

zhang yongyu

[Zhang yong yu, Manager]