







NTNV-11N20SISO-Ant1-2412




NTNV-11N20SISO-Ant1-2437




NTNV-11N20SISO-Ant1-2462



NTNV-11AX20SISO-Ant1-2412




NTNV-11AX20SISO-Ant1-2437




NTNV-11AX20SISO-Ant1-2462


Metal Antenna:




NTNV-11B-Ant1-2412




NTNV-11B-Ant1-2437




NTNV-11B-Ant1-2462




NTNV-11G-Ant1-2412




NTNV-11G-Ant1-2437




NTNV-11G-Ant1-2462




NTNV-11N20SISO-Ant1-2412




NTNV-11N20SISO-Ant1-2437




NTNV-11N20SISO-Ant1-2462



NTNV-11AX20SISO-Ant1-2412



NTNV-11AX20SISO-Ant1-2437



NTNV-11AX20SISO-Ant1-2462

APPENDIX PHOTOGRAPHS

Please refer to “ANNEX”

***** END OF REPORT *****