



802.11ax40_5270MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:30:05

802.11ax40_5310MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:31:52

802.11ax40_5270MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:28:30

802.11ax40_5310MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:29:12

802.11ax80_5290MHz_RU_Full_Chain 0



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:53:18


802.11ax80_5290MHz_RU_Full_Chain 1



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:37:04


5470-5725MHz

802.11a_5500MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 14:55:12

802.11a_5600MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 14:56:34

802.11a_5700MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 14:57:46

802.11a_5720MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 14:58:53

802.11a_5500MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:11:50

802.11a_5600MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:12:43

802.11a_5700MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:13:31

802.11a_5720MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:14:35

802.11ac20_5500MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:33:24

802.11ac20_5600MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:34:28

802.11ac20_5700MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:35:15

802.11ac20_5720MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:36:24

802.11ac20_5500MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:32:16

802.11ac20_5600MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:33:07

802.11ac20_5700MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:34:13

802.11ac20_5720MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:35:15

802.11ac40_5510MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:47:51

802.11ac40_5590MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:48:42

802.11ac40_5670MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:49:27

802.11ac40_5710MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:50:53

802.11ac40_5510MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:50:02

802.11ac40_5590MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:51:04

802.11ac40_5670MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:52:08

802.11ac40_5710MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:58:03

802.11ac80_5530MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:01:06

802.11ac80_5610MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:02:13

802.11ac80_5690MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:03:47

802.11ac80_5530MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:05:07

802.11ac80_5610MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:05:54

802.11ac80_5690MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:06:54

802.11ax20_5500MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:21:49

802.11ax20_5600MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:22:41

802.11ax20_5700MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:23:44

802.11ax20_5720MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:24:54

802.11ax20_5500MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:18:29

802.11ax20_5600MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:19:17

802.11ax20_5700MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:20:07

802.11ax20_5720MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:21:25

802.11ax40_5510MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:32:45

802.11ax40_5590MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:34:12

802.11ax40_5670MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:35:04

802.11ax40_5710MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:36:20

802.11ax40_5510MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:29:54

802.11ax40_5590MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:30:47

802.11ax40_5670MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:31:30

802.11ax40_5710MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:32:27

802.11ax80_5530MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:54:07

802.11ax80_5610MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:54:56

802.11ax80_5690MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:55:59

802.11ax80_5530MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:37:53

802.11ax80_5610MHz_RU_Full_Chain 1



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:38:42


802.11ax80_5690MHz_RU_Full_Chain 1



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:39:42


5725-5850MHz

802.11a_5745MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:06:52

802.11a_5785MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:07:49

802.11a_5825MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:08:46

802.11a_5745MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:15:32

802.11a_5785MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:16:27

802.11a_5825MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:17:20

802.11ac20_5745MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:37:21

802.11ac20_5785MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:38:13

802.11ac20_5825MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:39:38

802.11ac20_5745MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:36:03

802.11ac20_5785MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:37:55

802.11ac20_5825MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:39:10

802.11ac40_5755MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:52:30

802.11ac40_5795MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 15:54:08

802.11ac40_5755MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 17:59:53

802.11ac40_5795MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:00:40

802.11ac80_5775MHz_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:04:47

802.11ac80_5775MHz_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:07:41

802.11ax20_5745MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:25:50

802.11ax20_5785MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:26:44

802.11ax20_5825MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:27:38

802.11ax20_5745MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:22:13

802.11ax20_5785MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:23:00

802.11ax20_5825MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:23:47

802.11ax40_5755MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:37:25

802.11ax40_5795MHz_RU_Full_Chain 0




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:38:12

802.11ax40_5755MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:33:08

802.11ax40_5795MHz_RU_Full_Chain 1




ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:33:52

802.11ax80_5775MHz_RU_Full_Chain 0



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 16:58:20

802.11ax80_5775MHz_RU_Full_Chain 1



ProjectNo.:2601S14996E-RF Tester:Cheeb Huang
Date: 4.MAY.2026 18:40:30

Unwanted emissions inside the band 5150-5250 MHz**Test Information:**

Sample No.:	3JK9-2	Test Date:	2026/06/15
Test Site:	RF	Test Mode:	Transmitting
Tester:	Barry Feng, David He	Test Result:	Pass

Environmental Conditions:

Temperature: (°C)	25.2	Relative Humidity: (%)	51	ATM Pressure: (kPa)	100.8
----------------------	------	------------------------------	----	------------------------	-------