



5MHz\_High\_QPSK\_1@0(793MHz~806MHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 9 JUN 2026 10:34:02

5MHz\_High\_QPSK\_1@0(1559MHz~1610MHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 9 JUN 2026 10:40:03

10MHz\_Middle\_QPSK\_1@0(30MHz~8.87GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN 2026 13:15:15

10MHz\_Middle\_QPSK\_1@0(763MHz~775MHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 9 JUN 2026 10:34:46

10MHz\_Middle\_QPSK\_1@0(793MHz~806MHz)



ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 9 JUN 2026 10:34:58


10MHz\_Middle\_QPSK\_1@0(1559MHz~1610MHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 9 JUN 2026 10:41:04

**Band 17, Normal****1RB was the worst case**


5MHz\_Low\_QPSK\_1@0(30MHz~8.16GHz)

ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:19:34


5MHz\_Middle\_QPSK\_1@0(30MHz~8.16GHz)

ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:20:11


5MHz\_High\_QPSK\_1@0(30MHz~8.16GHz)

ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:20:47


10MHz\_Low\_QPSK\_1@0(30MHz~8.16GHz)

ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:21:27

10MHz\_Middle\_QPSK\_1@0(30MHz~8.16GHz)


ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:22:49

10MHz\_High\_QPSK\_1@0(30MHz~8.16GHz)

ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 6 JUN.2026 13:23:59


**Band 38, Normal****1RB was the worst case**

5MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:14:49

5MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:15:57

5MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:17:05

10MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:20:06

10MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:22:21

10MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Testers:Braylon Ma  
Date: 5 JUN.2026 17:24:37

15MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:27:50

15MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:30:06

15MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:32:25

20MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:36:09

20MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)



ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:39:23


20MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)



ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:40:38


**Band 41, Normal****1RB was the worst case**

5MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:42:56

5MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:44:04

5MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:45:12

10MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:47:23

10MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:49:38

10MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Testers: Bwaylon Ma  
Date: 5 JUN. 2026 17:52:00

15MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:55:26

15MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:57:40

15MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 17:59:54

20MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 18:05:55

20MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)



ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 18:08:10


20MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)



ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 5 JUN 2026 18:10:25


**Band 66, Normal****1RB was the worst case**

1.4MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:25:31

1.4MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:26:13

1.4MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:26:56

3MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:27:53

3MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:28:37

3MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Testert:Braylon Ma  
Date: 6.JUN.2026 13:29:19

5MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:30:42

5MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:31:24

5MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:32:06

10MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:32:52

10MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:34:18

10MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Braylon Ma  
Date: 6 JUN. 2026 13:35:41

15MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:37:09

15MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:38:34

15MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:39:59

20MHz\_Low\_QPSK\_1@0(30MHz~18.8GHz)




ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:41:25

20MHz\_Middle\_QPSK\_1@0(30MHz~18.8GHz)



ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:42:46

20MHz\_High\_QPSK\_1@0(30MHz~18.8GHz)



ProjectNo.: 2607T18667E-RF Tester: Breydon Ma  
Date: 6 JUN 2026 13:44:15