

Please upload an exhibit that explains how does the TCB verify the new agent information:

1- Is the address of the agent a valid physical US mailing address (not a US post office box, not a virtual mailbox, not P.O. Boxes, not a vacant lot, not a public building, etc.)

- We have checked if the address exists in a real and potential building (Google maps) + official US register, after this verification and the evidence below we can guarantee the following:
 - ✓ not a US post office box
 - ✓ not a virtual mailbox
 - ✓ not P.O. Boxes
 - ✓ not a vacant lot
 - ✓ not a public building(note)

► We checked the FCC FRN Search based on the information provided by the grantee.

Registration Detail	
FRN:	0033303629
Registration Date:	01/19/2023 04:57:13 PM
Last Updated:	04/29/2026 11:20:03 AM
Entity Name:	HP Tuners LLC
Entity Type:	Private Sector , Corporation
Contact Organization:	HP Tuners LLC
Contact Position:	Lead Hardware Engineer
Contact Name:	Mr Jerry Zdenek
Contact Address:	700 Eastwood Lane Buffalo Grove, IL 60089 United States
Contact Email:	regulatory@hptuners.com
ContactPhone:	(847) 465-8863
ContactFax:	

On the official register from :

HP TUNERS, LLC BRANCH

Company Number LLC_01185314

Native Company Number [01185314](#)

Status Active

Incorporation Date [Please log in to see this data](#)

Company Type Limited Liability Company

Jurisdiction [Illinois \(US\)](#)

Branch Branch of [HP TUNERS LLC \(Nevada \(US\)\)](#)

Registered Address 700 EASTWOOD LANE
BUFFALO GROVE
60089
IL
United States


Alternative Names HP TUNERS LLC (trading name, 2021-01-06 -)

Agent Name DAVID ARENBERG

Agent Address 700 EASTWOOD LN., BUFFALO GROVE, IL, 60089

Directors / Officers [3 officers available, please log in to see this data](#)

In google:



► **CONCLUSION by TCB:** The ASOP defined and provided by grantee is VALID and confirmed. Therefore the exhibit " C5266091_X23_Ed1_US_Agent_Letter" included in the file is ok.

2- Is the agent physically located at that valid US address such that the agent can be legally served at that address?

☒ Yes , check above

3- Has the listed agent clearly agreed in writing to serve as the agent for the grantee at that address?

☒ Yes, it is included in the exhibit " C5266091_X23_Ed1_US_Agent_Letter "

US Agent for Service of Process:

Company Name: HP Tuners LLC

FRN: 0033303629

Contact Name: Jerry Zdenek

Address: 700 Eastwood In, Buffalo Grove, Illinois 60089, United States

Telephone No: 847-465-8863

Email: regulatory@hptuners.com

Applicant:

Company name: HP Tuners LLC

Product Description: Render

Grantee code: 2BVWZ

FRN: 0033303629

FCC ID: 2BVWZ-REN50

Contact Name: Jerry Zdenek

Address: 700 Eastwood In, Buffalo Grove, Illinois 60089, United States

Telephone No.: 847-465-8863

Email: regulatory@hptuners.com

HP Tuners LLC certifies that, as of the date of this filing of the application with the TCB, HP Tuners LLC is our designated US agent for service of process for the above referenced FCC ID. HP Tuners LLC accepts to maintain an agent for no less than one year after the grantee has terminated all marketing and importation or the conclusion of any commission related proceeding involving equipment. HP Tuners LLC accepts, as of the date of the filing of the application, the obligation of the designated US agent for service of process for the above reference FCC ID.

The US Agent for Service of Process is aware of and agrees to comply with the requirements outlined in the FCC Equipment Authorization Program, Report and Order FCC 22-84, and clause § 2.911.

The Applicant is aware of and agrees to comply with the requirements outlined in the FCC Equipment Authorization Program, Report and Order FCC 22-84, and clause § 2.911.

Date: 2026/5/20

Applicant's Name: Jerry Zdenek	US Agent's Name: Jerry Zdenek
Title: Lead Hardware Engineer	Title: Lead Hardware Engineer
Signature 	Signature 