


External Photos

Outview: iAeris6 Pic 1




Outview: iAeris6 Pic 2




Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Outview: iAeris6 Pic 3




Outview: iAeris6 Pic 4




Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Outview: iAeris6 Pic 5



Outview: iAeris6 Pic 6




Outview: iAeris6 Pic 7



Accessory: Adapter(US) Pic 1



Accessory: Adapter(US) Pic 2



Underwriters Laboratories Taiwan Co., Ltd.

Building A, B and E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Accessory: Adapter(US) Pic 3**Accessory: Adapter(US) Pic 4**

Accessory: Adapter(US) Pic 5

