

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A

INTERNAL PHOTOGRAPHS




Figure 1. Outer Shell Removed, Upright 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A



Figure 2. Outer Shell Removed, Upright 2



Figure 3. Outer Shell Removed, Side 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A



Figure 4. Outer Shell Removed, Side 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A



Figure 5. Main PCB in Ring (covered in clear epoxy)

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A




Figure 6. EUT, PCB Back

Note: Wire coming off board are for programming and power purposes of testing.

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A




Figure 7. EUT, PCB Front

Note: Wire coming off board are for programming and power purposes of testing.

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2BXSX-NXRING1
26-0214
October 8, 2026
GenAI Healthcare Inc.
NX01A




Figure 8. Closeup of Radio and Antenna