

Q

HONDA ACCESSORY

P/N: XXXXX-30A-XXXX-M1

REF NO.: XXXXXXX

AH00ICB

S/N: XXXXXXXXXXXXXXXX

ASSEMBLED IN MEXICO YY/MM

FCC ID: A269ZUA165

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.


IC: 700B-UA165

ALPSALPINE

ALPS ALPINE CO., LTD.



ADDRESS: Avenida Industrial Del Norte
L5-1 Parque Industrial Del Norte 8 8730
Ciudad Reynosa, Tamaulipas, Mexico

FCC ID Font size : 5.7pt

V1

HONDA ACCESSORY			X-XX-XXX-XXXXXXXXXXXXXXXXXX		RAMATEL X-XXXXX
P/N: XXXXX-30A-XXXX-M1					
REF NO.: XXXXXXXX					
AH00ICB 1					
S/N: XXXXXXXXXXXXXXXX					
ASSEMBLED IN MEXICO YY/MM					
FCC ID: A269ZUA165					
This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.					
IC: 700B-UA165	PARAGUAY Distributor Name: VICAR S.A. ADDRESS: AV. EUSEBIO AYALA KM 4 1/2 ESQ CAMILO RECALDE ASUNCI_N, PARAGUAY		 CONATEL		
	IFETEL+XXXX-XXXX	NR: XXXX-XX-X-XXXXXX			
		 ALPS ALPINE CO., LTD. ADDRESS: Avenida Industrial Del Norte L5-1 Parque Industrial Del Norte 8 8730 Ciudad Reynosa, Tamaulipas, Mexico			
					

FCC ID Font size : 5.7pt

