


INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B



INTERTEK TESTING SERVICE

Report No.: 16030425HKG-001

Equipment Photographs

Model: CD6929B

(Internal)



FCC ID: A2H-RS2929B
IC: 9903A-RS2929B