


INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250



INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250



INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250


INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250


INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250



INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250

INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250
IC: 9903A-ABX3250


INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14010723HKG-002

Equipment Photographs

Model: ABX3250KN

(Internal)



FCC ID: A2HABX3250

IC: 9903A-ABX3250