


INTERTEK TESTING SERVICE

Report No: 15011110HKG-001

Equipment Photographs

Model: CT9213W87

(Internal)



FCC ID: A2HRCT6213W87

IC: 9903A-RCT6213W87

INTERTEK TESTING SERVICE

Report No: 15011110HKG-001

Equipment Photographs

Model: CT9213W87

(Internal)



FCC ID: A2HRCT6213W87

IC: 9903A-RCT6213W87



INTERTEK TESTING SERVICE

Report No: 15011110HKG-001

Equipment Photographs

Model: CT9213W87

(Internal)



FCC ID: A2HRCT6213W87

IC: 9903A-RCT6213W87



INTERTEK TESTING SERVICE

Report No: 15011110HKG-001

Equipment Photographs

Model: CT9213W87


(Internal)



FCC ID: A2HRCT6213W87

IC: 9903A-RCT6213W87

Report No: 15011110HKG-001





INTERTEK TESTING SERVICE

Report No: 15011110HKG-001

Equipment Photographs

Model: CT9213W87

(Internal)



FCC ID: A2HRCT6213W87

IC: 9903A-RCT6213W87