

INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26

INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26


INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26


INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26



INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26


INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26



INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26



INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26



INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)



FCC ID: A2HRCT6273W26

IC: 9903A-RCT6273W26

INTERTEK TESTING SERVICE

Report No.: 14040046HKG-002

Equipment Photographs

Model: CT9273W26

(Internal)

