

## INTERTEK TESTING SERVICE


---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



---

FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

## INTERTEK TESTING SERVICE



---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



---

FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

## INTERTEK TESTING SERVICE


---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



---

FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

## INTERTEK TESTING SERVICE

---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



---

FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

# INTERTEK TESTING SERVICE

Report No.: 15011112HKG-001

## Equipment Photographs

Model: CT9303W87

(Internal)



FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87

## INTERTEK TESTING SERVICE

---

Report No.: 15011112HKG-001

### Equipment Photographs

Model: CT9303W87

(Internal)



---

FCC ID: A2HRCT6303W87

IC: 9903A-RCT6303W87