


INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15030653HKG-001

Equipment Photographs

Model: SBT1739BWS

(Internal)

