



INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15071300HKG-001

Equipment Photographs

Model: SBT1739BWSE

(Internal)

