



INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)



FCC ID: A2HSPS3688B

IC: 9903A-SPS3688B



INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)



FCC ID: A2HSPS3688B

IC: 9903A-SPS3688B



INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)



FCC ID: A2HSPS3688B

IC: 9903A-SPS3688B



INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14090268HKG-002

Equipment Photographs

Model: KLR33688B

(Internal)



FCC ID: A2HSPS3688B

IC: 9903A-SPS3688B