



INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)



FCC ID: A2HW101

IC: 9903A-W101


INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)



FCC ID: A2HW101

IC: 9903A-W101

INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)



FCC ID: A2HW101

IC: 9903A-W101


INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15041543HKG-001

Equipment Photographs

Model: WT19303W87

(Internal)

