10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP

ANTENNA PORT CONDUCTED PHOTO



This report shall not be reproduced except in full, without the written approval of UL CCS.

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION

X-AXIS FRONT PHOTO



COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.

X-AXIS BACK PHOTO



COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.

Y-AXIS FRONT PHOTO

This report shall not be reproduced except in full, without the written approval of UL CCS.

Y-AXIS BACK PHOTO



COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.

Z-AXIS FRONT PHOTO

COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.

Z-AXIS BACK PHOTO

This report shall not be reproduced except in full, without the written approval of UL CCS.

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

AC ADAPTER CHARGE MODE

LINE CONDUCTED FRONT PHOTO

COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.

LINE CONDUCTED BACK PHOTO



END OF REPORT

COMPLIANCE CERTIFICATION SERVICES (UL CCS) FORM NO: CCSUP4701D
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL CCS.