




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (2210) / (2355)
Pages

ANT57

QPSK




16QAM




ANT58

QPSK




16QAM




ANT59

QPSK




16QAM




ANT60

QPSK




16QAM




ANT61

QPSK





16QAM



ANT62

QPSK





16QAM




ANT63

QPSK




16QAM




ANT64

QPSK





16QAM




BW 100MHz +100MHz, Multi carrier(Contiguous)

ANT1

QPSK





16QAM



ANT2

QPSK




16QAM




ANT3

QPSK




16QAM





ANT4

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (2222) / (2355)
Pages

ANT5

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (2223) / (2355)
Pages

ANT6

QPSK





16QAM




ANT7

QPSK




16QAM




ANT8

QPSK



16QAM



ANT9

QPSK




16QAM



ANT10

QPSK




16QAM



ANT11

QPSK




16QAM



ANT12

QPSK




16QAM



ANT13

QPSK




16QAM



ANT14

QPSK





16QAM




ANT15

QPSK





16QAM



ANT16

QPSK




16QAM



ANT17

QPSK





16QAM






Report No.:
CTK-2020-04662
Page (2235) / (2355)
Pages

QPSK

[illegible]

ANT20

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (2238) / (2355)
Pages

ANT21

QPSK




16QAM




ANT22

QPSK



16QAM




ANT23

QPSK





16QAM





ANT24

QPSK





16QAM



ANT25

QPSK





16QAM




ANT26

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (2244) / (2355)
Pages

ANT27

QPSK



16QAM







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2020-04662
Page (2245) / (2355)
Pages

ANT28

QPSK





16QAM




ANT29

QPSK



16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (2247) / (2355)
Pages


ANT30

QPSK




16QAM






QPSK




16QAM




ANT32

QPSK




16QAM




ANT33

QPSK





16QAM



ANT34

QPSK





16QAM




ANT35

QPSK



16QAM



ANT36

QPSK




16QAM




ANT37

QPSK





16QAM




ANT38

QPSK





16QAM




ANT39

QPSK





16QAM





ANT40

QPSK




16QAM



ANT41

QPSK



16QAM



ANT42

QPSK





16QAM



ANT43

QPSK



16QAM

