







HOUSEHOLD MICROWAVE OVEN WITH REMOVABLE TURNING PLATE				
MODEL NO.	DAEWOO	TYPE	OT	OT
MAX. CAPACITY	2.0 LITERS	POWER	800 W	800 W
MANUFACTURED BY	SAMSUNG ELECTRONICS CO., LTD.	MADE IN	KOREA	KOREA
PROD. NO.	00U0538-1	DATE OF ISSUE	12/19/00	12/19/00

CAUTION THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING TO ENSURE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK, ALWAYS CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

WARNING CERTAIN INTERNAL PARTS ARE INTENDED TO BE NOT TOUCHED AND MAY PRESENT A RISK OF ELECTRICAL SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, LOW VOLTAGE TRANSFORMER, TOUCH CONTROL, TYPED THERMISTOR, MOUNTING BRACKET (MICROWAVE TUBE).

WARNING RISK OF ELECTRIC SHOCK: NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.

NOT FOR BUILD-IN INSTALLATION



SAMSUNG**HOUSEHOLD MICROWAVE OVEN**
416 MAETANDONG, SUWON, KOREAMODEL NO.
MW630WA

SERIAL NO.

120Vac

60Hz

1.1 kW
MICROWAVE
HEATER

LISTED



725F

MANUFACTURED : NOVEMBER-2000

FCC ID : A3LMW610

MADE IN KOREA

SEC

THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J.

CAUTION THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING • TO ENSURE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK HAZARD CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.
• DISCONNECT APPLIANCE BEFORE SERVICING REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

WARNING CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRICAL SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL- DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED : FAN MOTOR, HIGH VOLTAGE TRANSFORMER (TOUCH CONTROL TYPE), TIMER & TIMER MECHANICAL TYPE).

