





SCHEMATIC DIAGRAM

WARNING
POWER MUST BE DISCONNECTED
BEFORE SERVICING THIS APPLIANCE


MODEL NO. : JVM-1950/DVM-1950/PVM-1970



WIRING DIAGRAM

WARNING
POWER MUST BE DISCONNECTED
BEFORE SERVICING THIS APPLIANCE

MODEL NO. : JVM-1950/DVM-1950/PVM-1970



NOTE: FOR SERVICING REPLACEMENT USE THE APPROPRIATE
THERMOPLASTIC COVERED WIRE EXCEPT FOR
HIGH VOLTAGE LEADS OR AS NOTED ON SPECIAL LEADS.

Printed in Malaysia