


# SCHEMATIC DIAGRAM

WARNING  
POWER MUST BE DISCONNECTED  
BEFORE SERVICING THIS APPLIANCE

MODEL NO. : PVM-2170

| COLOR  | SYMBOL |
|--------|--------|
| GRAY   | GR     |
| WHITE  | W      |
| BLACK  | B      |
| RED    | R      |
| BLUE   | BL     |
| ORANGE | O      |
| YELLOW | Y      |
| GREEN  | G      |
| PINK   | P      |
| AZURE  | A      |
| VIOLET | V      |
| BROWN  | BR     |

GROUND




# WIRING DIAGRAM

WARNING  
POWER MUST BE DISCONNECTED  
BEFORE SERVICING THIS APPLIANCE

MODEL NO. : PVM-2170

| COLOR  | SYMBOL |
|--------|--------|
| GRAY   | GRA    |
| WHITE  | WHT    |
| BLACK  | BLK    |
| RED    | RED    |
| BLUE   | BLU    |
| ORANGE | ORG    |
| YELLOW | YEL    |
| GREEN  | GRN    |
| PINK   | PIN    |
| AZURE  | AZU    |
| VIOLET | VIL    |
| BROWN  | BRN    |

GROUND  
HARNES LEADS  
PARTS LEADS



NOTE: FOR SERVICING REPLACEMENT USE THE APPROPRIATE  
THERMOPLASTIC COVERED WIRE EXCEPT FOR  
HIGH VOLTAGE LEADS OR AS NOTED ON SPECIAL LEADS.

Printed in Malaysia

