

LTE B4 5MHz QPSK Low Channel RB1-0



LTE B4 5MHz QPSK Mid Channel RB1-0



LTE B4 5MHz QPSK High Channel RB1-0



LTE B4 5MHz 16QAM Low Channel RB1-0



LTE B4 5MHz 16QAM Mid Channel RB1-0



LTE B4 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B4 10MHz QPSK Low Channel RB1-0



LTE B4 10MHz QPSK Mid Channel RB1-0



LTE B4 10MHz QPSK High Channel RB1-0



LTE B4 10MHz 16QAM Low Channel RB1-0



LTE B4 10MHz 16QAM Mid Channel RB1-0



LTE B4 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B4 15MHz QPSK Low Channel RB1-0



LTE B4 15MHz QPSK Mid Channel RB1-0



LTE B4 15MHz QPSK High Channel RB1-0



LTE B4 15MHz 16QAM Low Channel RB1-0



LTE B4 15MHz 16QAM Mid Channel RB1-0



LTE B4 15MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B4 20MHz QPSK Low Channel RB1-0



LTE B4 20MHz QPSK Mid Channel RB1-0



LTE B4 20MHz QPSK High Channel RB1-0



LTE B4 20MHz 16QAM Low Channel RB1-0



LTE B4 20MHz 16QAM Mid Channel RB1-0



LTE B4 20MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.3.8. LTE BAND 5



LTE B5 1.4MHz QPSK Low Channel RB1-0



LTE B5 1.4MHz QPSK Mid Channel RB1-0



LTE B5 1.4MHz QPSK High Channel RB1-0



LTE B5 1.4MHz 16QAM Low Channel RB1-0



LTE B5 1.4MHz 16QAM Mid Channel RB1-0



LTE B5 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 3MHz QPSK Low Channel RB1-0



LTE B5 3MHz QPSK Mid Channel RB1-0



LTE B5 3MHz QPSK High Channel RB1-0



LTE B5 3MHz 16QAM Low Channel RB1-0



LTE B5 3MHz 16QAM Mid Channel RB1-0



LTE B5 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 5MHz QPSK Low Channel RB1-0



LTE B5 5MHz QPSK Mid Channel RB1-0



LTE B5 5MHz QPSK High Channel RB1-0



LTE B5 5MHz 16QAM Low Channel RB1-0



LTE B5 5MHz 16QAM Mid Channel RB1-0



LTE B5 5MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B5 10MHz QPSK Low Channel RB1-0



LTE B5 10MHz QPSK Mid Channel RB1-0



LTE B5 10MHz QPSK High Channel RB1-0



LTE B5 10MHz 16QAM Low Channel RB1-0



LTE B5 10MHz 16QAM Mid Channel RB1-0



LTE B5 10MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.3.9. LTE BAND 12



LTE B12 1.4MHz QPSK Low Channel RB1-0



LTE B12 1.4MHz QPSK Mid Channel RB1-0



LTE B12 1.4MHz QPSK High Channel RB1-0



LTE B12 1.4MHz 16QAM Low Channel RB1-0



LTE B12 1.4MHz 16QAM Mid Channel RB1-0



LTE B12 1.4MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 3MHz QPSK Low Channel RB1-0



LTE B12 3MHz QPSK Mid Channel RB1-0



LTE B12 3MHz QPSK High Channel RB1-0



LTE B12 3MHz 16QAM Low Channel RB1-0



LTE B12 3MHz 16QAM Mid Channel RB1-0



LTE B12 3MHz 16QAM High Channel RB1-0

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.