

**HCT Co., Ltd.**

74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA
Tel. +82 31 634 6300 Fax. +82 31 645 6401

Appendix A: Test Setup Photo

FCC ID

A3LSMN981B

File No.

HCT-RF-2006-FC039-P

HCT-RF-2006-FC044-P

HCT-RF-2006-FC040-P

HCT-RF-2006-FC045-P

HCT-RF-2006-FC041-P

HCT-RF-2006-FC070-P

HCT-RF-2006-FC042-P

HCT-RF-2006-FC043-P


REVISION HISTORY

The revision history for this document is shown in table.


Revision No.	Date of Issue	Description
0	June 30, 2020	Initial Release


File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		

1. Radiated Test Setup Photo



File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		






File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		




File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		





File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		





File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		














2. Conducted Test Setup Photo



File	HCT-RF-2006-FC039-P	HCT-RF-2006-FC040-P	HCT-RF-2006-FC041-P	HCT-RF-2006-FC042-P	HCT-RF-2006-FC043-P
No.	HCT-RF-2006-FC044-P	HCT-RF-2006-FC045-P	HCT-RF-2006-FC070-P		