





Description of Changes

Changes are as below.

Item	Antenna_Left	Antenna Gain
Before		-7.3 dBi
After		-7.5 dBi

Item	Main board_Front		Main board_Rear	
Before				
After				

Note

- There is change of the antenna pattern.
Equivalent antenna.
 - Lower antenna gain.
 - Same antenna type.
- There is minor change in PCB layout.
Minor change in PCB layout does not affect to radio performance.