

Description of Changes

Changes are as below.

Enabling new RF function by software		
	Before	After
13.56MHz NFC	One 13.56MHz NFC function 1. NTAG for Wireless Charging	Two 13.56MHz NFC function 1. NTAG for Wireless Charging 2. PN553 for Tagging Communication
	NFC(PN553) was disabled by software.	NFC(PN553) is enabled by software
	FVIN : SC9	FVIN : SC9(NFC)
	The device is identical to the previous device except for enabling new RF function by software as above.	

Software(FVIN) changes described in this document doesn't affect the radio performance of this device and there is no change of power setting level.

New Software version(FVIN) is identical to previous one. Only name of Software version was changed.

There are no any changes except for changes above.

Items	Before	After	Remark
Antenna	-	No change	
Max.outputpower	-	No change	