

**Internal View of EUT**

*The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.*


**SGS Testing Korea Co., Ltd.** 18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371


[www.sgstesting.co.kr](http://www.sgstesting.co.kr)

---

## Top View of Main-board



## Bottom View of Main-board




*The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.*

**SGS Testing Korea Co., Ltd.** 18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371

[www.sgstesting.co.kr](http://www.sgstesting.co.kr)

## Removed RF Shielding of Main-board



## Connected Antenna of Main-board



*The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.*

**SGS Testing Korea Co., Ltd.** 18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371

[www.sgstesting.co.kr](http://www.sgstesting.co.kr)

---