



HCT Co., Ltd.

2-6, 73, 74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, Republic of Korea

Tel. +82 31 645 6300 Fax. +82 31 645 6401

Appendix A: Test Setup Photo

FCC ID
A3LSMX526B

File No.

HCT-RF-2502-FC036-P	HCT-RF-2502-FC037-P	HCT-RF-2502-FC038-P
HCT-RF-2502-FC039-P	HCT-RF-2502-FC040-P	HCT-RF-2502-FC041-P
HCT-RF-2502-FC042-P	HCT-RF-2502-FC043-P	HCT-RF-2502-FC044-P
HCT-RF-2502-FC045-P	HCT-RF-2502-FC046-P	HCT-RF-2502-FC047-P
HCT-RF-2502-FC048-P	HCT-RF-2502-FC049-P	


REVISION HISTORY

The revision history for this document is shown in table.


Revision No.	Date of Issue	Description
0	February 17, 2025	Initial Release

File No.	HCT-RF-2502-FC036-P	HCT-RF-2502-FC037-P	HCT-RF-2502-FC038-P	HCT-RF-2502-FC039-P	HCT-RF-2502-FC040-P
	HCT-RF-2502-FC041-P	HCT-RF-2502-FC042-P	HCT-RF-2502-FC043-P	HCT-RF-2502-FC044-P	HCT-RF-2502-FC045-P
	HCT-RF-2502-FC046-P	HCT-RF-2502-FC047-P	HCT-RF-2502-FC048-P	HCT-RF-2502-FC049-P	


1. Radiated Test Setup Photo



File No.	HCT-RF-2502-FC036-P	HCT-RF-2502-FC037-P	HCT-RF-2502-FC038-P	HCT-RF-2502-FC039-P	HCT-RF-2502-FC040-P
	HCT-RF-2502-FC041-P	HCT-RF-2502-FC042-P	HCT-RF-2502-FC043-P	HCT-RF-2502-FC044-P	HCT-RF-2502-FC045-P
	HCT-RF-2502-FC046-P	HCT-RF-2502-FC047-P	HCT-RF-2502-FC048-P	HCT-RF-2502-FC049-P	



File No.	HCT-RF-2502-FC036-P	HCT-RF-2502-FC037-P	HCT-RF-2502-FC038-P	HCT-RF-2502-FC039-P	HCT-RF-2502-FC040-P
	HCT-RF-2502-FC041-P	HCT-RF-2502-FC042-P	HCT-RF-2502-FC043-P	HCT-RF-2502-FC044-P	HCT-RF-2502-FC045-P
	HCT-RF-2502-FC046-P	HCT-RF-2502-FC047-P	HCT-RF-2502-FC048-P	HCT-RF-2502-FC049-P	



File
No.

HCT-RF-2502-FC036-P
HCT-RF-2502-FC041-P
HCT-RF-2502-FC046-P

HCT-RF-2502-FC037-P
HCT-RF-2502-FC042-P
HCT-RF-2502-FC047-P

HCT-RF-2502-FC038-P
HCT-RF-2502-FC043-P
HCT-RF-2502-FC048-P

HCT-RF-2502-FC039-P
HCT-RF-2502-FC044-P
HCT-RF-2502-FC049-P

HCT-RF-2502-FC040-P
HCT-RF-2502-FC045-P