9.5.3. 802.11ax HE40 MODE 2TX IN THE UNII-5 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 484T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.4. 802.11ax HE80 MODE 2TX IN THE UNII-5 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 996T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.5. 802.11ax HE160 MODE 2TX IN THE UNII-5 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 2x996T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.6. 802.11a MODE 2TX IN THE UNII-6 BAND

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.7. 802.11ax HE20 MODE 2TX IN THE UNII-6 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 26T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 52T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID

MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0

HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400

This report shall not be reproduced except in full, without the written approval of UL LLC

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 106T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 242T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.8. 802.11ax HE40 MODE 2TX IN THE UNII-6 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 484T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.9. 802.11ax HE80 MODE 2TX IN THE UNII-6 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 996T

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.10. 802.11ax HE160 MODE 2TX IN THE UNII-6 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 2x996T

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.11. 802.11a MODE 2TX IN THE UNII-7 BAND

LOW



LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400

This report shall not be reproduced except in full, without the written approval of UL LLC

9.5.12. 802.11ax HE20 MODE 2TX IN THE UNII-7 BAND

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 26T

LOW

LOW CHANNEL CHAIN 0

LOW CHANNEL CHAIN 1

MID

MID CHANNEL CHAIN 0

MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH

HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400

This report shall not be reproduced except in full, without the written approval of UL LLC

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 52T

LOW

LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID

MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC

HIGH



HIGH CHANNEL CHAIN 0



HIGH CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400

This report shall not be reproduced except in full, without the written approval of UL LLC

2TX CHAIN 0 + CHAIN 1 CDD OFDMA MODE: 106T

LOW

LOW CHANNEL CHAIN 0



LOW CHANNEL CHAIN 1

MID



MID CHANNEL CHAIN 0



MID CHANNEL CHAIN 1

UL LLC
12 Laboratory Drive, Research Triangle Park, NC 27709; USA TEL:(919)549-1400
This report shall not be reproduced except in full, without the written approval of UL LLC