


7 MEASUREMENT PHOTOS

Photo 7.1 Setup with the Maximized RFI Voltage Emission Level



Photo 7.2 Setup with the Maximized RFI Field Strength Emission Level



1. The first step in the process is to identify the problem or issue that needs to be addressed.

2. The second step is to gather information and data related to the problem.

3. The third step is to analyze the information and data to identify the root cause of the problem.

4. The fourth step is to develop a plan of action to address the problem.

5. The fifth step is to implement the plan of action and monitor the results.

6. The sixth step is to evaluate the results and make adjustments as needed.

7. The seventh step is to document the process and results for future reference.

8. The eighth step is to communicate the results to the relevant stakeholders.

9. The ninth step is to review the process and make improvements as needed.

10. The tenth step is to conclude the process and move on to the next task.