















ANT1_802.11a_UNII 2C






ANT1_802.11a_UNII 3






ANT2_802.11a_UNII 1






ANT2_802.11a_UNII 2A






ANT2_802.11a_UNII 2C






ANT2_802.11a_UNII 3






ANT1_802.11n_HT20_UNII 1






ANT1_802.11n_HT20_UNII 2A






ANT1_802.11n_HT20_UNII 2C






ANT1_802.11n_HT20_UNII 3






ANT2_802.11n_HT20_UNII 1






ANT2_802.11n_HT20_UNII 2A






ANT2_802.11n_HT20_UNII 2C






ANT2_802.11n_HT20_UNII 3






ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






ANT2_802.11ac_VHT20_UNII 1






ANT2_802.11ac_VHT20_UNII 2A






ANT2_802.11ac_VHT20_UNII 2C






ANT2_802.11ac_VHT20_UNII 3






ANT1_802.11ax_HE20_UNII 1






ANT1_802.11ax_HE20_UNII 2A






ANT1_802.11ax_HE20_UNII 2C






ANT1_802.11ax_HE20_UNII 3






ANT2_802.11ax_HE20_UNII 1





ANT2_802.11ax_HE20_UNII 2A





ANT2_802.11ax_HE20_UNI1 2C






ANT2_802.11ax_HE20_UNI1 3





ANT1_802.11n_HT40_UNII 1





ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C






ANT1_802.11n_HT40_UNI1 3



ANT2_802.11n_HT40_UNII 1



ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03418
Page (160) / (376) Pages






ANT2_802.11n_HT40_UNII 3



ANT1_802.11ac_VHT40_UNI1 1



ANT1_802.11ac_VHT40_UNI1 2A





ANT1_802.11ac_VHT40_UNI1 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03418
Page (162) / (376) Pages







ANT1_802.11ac_VHT40_UNII 3



ANT2_802.11ac_VHT40_UNI1 1



ANT2_802.11ac_VHT40_UNI1 2A





ANT2_802.11ac_VHT40_UNI1 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03418
Page (164) / (376) Pages






ANT2_802.11ac_VHT40_UNII 3



ANT1_802.11ax_HE40_UNII 1



ANT1_802.11ax_HE40_UNII 2A





ANT1_802.11ax_HE40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03418
Page (166) / (376) Pages






ANT1_802.11ax_HE40_UNI 3



ANT2_802.11ax_HE40_UNII 1



ANT2_802.11ax_HE40_UNII 2A





ANT2_802.11ax_HE40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (168) / (376) Pages



ANT2_802.11ax_HE40_UNI 3