















ANT1_802.11ax_HE20_26T_High_UNII 2C






ANT1_802.11ax_HE20_26T_High_UNII 3






ANT2_802.11ax_HE20_26T_High_UNII 1





ANT2_802.11ax_HE20_26T_High_UNII 2A





ANT2_802.11ax_HE20_26T_High_UNII 2C






ANT2_802.11ax_HE20_26T_High_UNII 3





ANT1_802.11n_HT40_UNII 1





ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C






ANT1_802.11n_HT40_UNI1 3





ANT2_802.11n_HT40_UNII 1





ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C






ANT2_802.11n_HT40_UNII 3





ANT1_802.11ac_VHT40_UNII 1





ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C





ANT1_802.11ac_VHT40_UNI1 3




ANT2_802.11ac_VHT40_UNII 1





ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C





ANT2_802.11ac_VHT40_UNII 3




ANT1_802.11ax_HE40_SU_UNII 1





ANT1_802.11ax_HE40_SU_UNII 2A





ANT1_802.11ax_HE40_SU_UNII 2C





ANT1_802.11ax_HE40_SU_UNII 2C






ANT1_802.11ax_HE40_SU_UNI 3





ANT2_802.11ax_HE40_SU_UNII 1





ANT2_802.11ax_HE40_SU_UNII 2A





ANT2_802.11ax_HE40_SU_UNII 2C






ANT2_802.11ax_HE40_SU_UNI 3



ANT1_802.11ax_HE40_26T_Low_UNII 1



ANT1_802.11ax_HE40_26T_Low_UNII 2A





ANT1_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03422
Page (78) / (373) Pages






ANT1_802.11ax_HE40_26T_Low_UNII 3



ANT2_802.11ax_HE40_26T_Low_UNII 1



ANT2_802.11ax_HE40_26T_Low_UNII 2A





ANT2_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03422
Page (80) / (373) Pages






ANT2_802.11ax_HE40_26T_Low_UNI 3





ANT1_802.11ax_HE40_26T_Mid_UNI1 1





ANT1_802.11ax_HE40_26T_Mid_UNI1 2A





ANT1_802.11ax_HE40_26T_Mid_UNI1 2C






ANT1_802.11ax_HE40_26T_Mid_UNI1 3





ANT2_802.11ax_HE40_26T_Mid_UNII 1





ANT2_802.11ax_HE40_26T_Mid_UNII 2A





ANT2_802.11ax_HE40_26T_Mid_UNII 2C






ANT2_802.11ax_HE40_26T_Mid_UNI1 3



ANT1_802.11ax_HE40_26T_High_UNII 1



ANT1_802.11ax_HE40_26T_High_UNII 2A





ANT1_802.11ax_HE40_26T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-03422
Page (86) / (373) Pages






ANT1_802.11ax_HE40_26T_High_UNI 3



ANT2_802.11ax_HE40_26T_High_UNII 1



ANT2_802.11ax_HE40_26T_High_UNII 2A





ANT2_802.11ax_HE40_26T_High_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (88) / (373) Pages



ANT2_802.11ax_HE40_26T_High_UNI1 3