






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (280) / (427) Pages





ANT1_802.11ax_HE80_52T_Low_UNII 5






ANT1_802.11ax_HE80_52T_Low_UNII 6




ANT1_802.11ax_HE80_52T_Low_UNII 7






ANT1_802.11ax_HE80_52T_Low_UNII 8





ANT0_802.11ax_HE80_52T_Mid_UNII 5






ANT0_802.11ax_HE80_52T_Mid_UNII 6




ANT0_802.11ax_HE80_52T_Mid_UNII 7






ANT0_802.11ax_HE80_52T_Mid_UNII 8





ANT1_802.11ax_HE80_52T_Mid_UNII 5



ANT1_802.11ax_HE80_52T_Mid_UNII 6



ANT1_802.11ax_HE80_52T_Mid_UNII 7






ANT1_802.11ax_HE80_52T_Mid_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (286) / (427) Pages





ANT0_802.11ax_HE80_52T_High_UNII 5



ANT0_802.11ax_HE80_52T_High_UNII 6



ANTO_802.11ax_HE80_52T_High_UNII 7



ANTO_802.11ax_HE80_52T_High_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (288) / (427) Pages





ANT1_802.11ax_HE80_52T_High_UNII 5






ANT1_802.11ax_HE80_52T_High_UNII 6




ANT1_802.11ax_HE80_52T_High_UNII 7



ANT1_802.11ax_HE80_52T_High_UNII 8



ANT0_802.11ax_HE80_106T_Low_UNII 5






ANT0_802.11ax_HE80_106T_Low_UNII 6





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (291) / (427) Pages



ANTO_802.11ax_HE80_106T_Low_UNII 7





ANTO_802.11ax_HE80_106T_Low_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (292) / (427) Pages



ANT1_802.11ax_HE80_106T_Low_UNII 5






ANT1_802.11ax_HE80_106T_Low_UNII 6





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (293) / (427) Pages



ANT1_802.11ax_HE80_106T_Low_UNII 7






ANT1_802.11ax_HE80_106T_Low_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (294) / (427) Pages





ANT0_802.11ax_HE80_106T_Mid_UNII 5



ANT0_802.11ax_HE80_106T_Mid_UNII 6



ANTO_802.11ax_HE80_106T_Mid_UNII 7






ANTO_802.11ax_HE80_106T_Mid_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (296) / (427) Pages





ANT1_802.11ax_HE80_106T_Mid_UNII 5






ANT1_802.11ax_HE80_106T_Mid_UNII 6




ANT1_802.11ax_HE80_106T_Mid_UNII 7






ANT1_802.11ax_HE80_106T_Mid_UNII 8





ANT0_802.11ax_HE80_106T_High_UNII 5



ANT0_802.11ax_HE80_106T_High_UNII 6



ANTO_802.11ax_HE80_106T_High_UNII 7






ANTO_802.11ax_HE80_106T_High_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (300) / (427) Pages



ANT1_802.11ax_HE80_106T_High_UNII 5






ANT1_802.11ax_HE80_106T_High_UNII 6





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (301) / (427) Pages



ANT1_802.11ax_HE80_106T_High_UNII 7






ANT1_802.11ax_HE80_106T_High_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (302) / (427) Pages





ANT0_802.11ax_HE80_242T_Low_UNII 5



ANT0_802.11ax_HE80_242T_Low_UNII 6



ANTO_802.11ax_HE80_242T_Low_UNII 7






ANTO_802.11ax_HE80_242T_Low_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (304) / (427) Pages





ANT1_802.11ax_HE80_242T_Low_UNII 5



ANT1_802.11ax_HE80_242T_Low_UNII 6




ANT1_802.11ax_HE80_242T_Low_UNII 7






ANT1_802.11ax_HE80_242T_Low_UNII 8





Report No.:
CTK-2023-00952
Page (306) / (427) Pages





ANTO_802.11ax_HE80_242T_Mid_UNII 7






ANTO_802.11ax_HE80_242T_Mid_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (308) / (427) Pages





ANT1_802.11ax_HE80_242T_Mid_UNII 5



ANT1_802.11ax_HE80_242T_Mid_UNII 6



ANT1_802.11ax_HE80_242T_Mid_UNII 7






ANT1_802.11ax_HE80_242T_Mid_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (310) / (427) Pages





ANT0_802.11ax_HE80_242T_High_UNII 5



ANT0_802.11ax_HE80_242T_High_UNII 6



ANTO_802.11ax_HE80_242T_High_UNII 7






ANTO_802.11ax_HE80_242T_High_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (312) / (427) Pages





ANT1_802.11ax_HE80_242T_High_UNII 5



ANT1_802.11ax_HE80_242T_High_UNII 6



ANT1_802.11ax_HE80_242T_High_UNII 7






ANT1_802.11ax_HE80_242T_High_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (314) / (427) Pages



ANT0_802.11ax_HE80_484T_Low_UNII 5



ANT0_802.11ax_HE80_484T_Low_UNII 6