









CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (58) / (158) Pages






ANT0, 802.11g



ANT1, 802.11g



ANT0, 802.11n_HT20






ANT1, 802.11n_HT20






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (60) / (158) Pages






ANT0, 802.11n_HT40



ANT1, 802.11n_HT40



ANT0, 802.11ax_HE20_26T_Low






ANT1, 802.11ax_HE20_26T_Low






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (62) / (158) Pages






ANT0, 802.11ax_HE20_26T_Mid






ANT1, 802.11ax_HE20_26T_Mid






ANT0, 802.11ax_HE20_26T_High






ANT1, 802.11ax_HE20_26T_High






ANT0, 802.11ax_HE20_52T_Low






ANT1, 802.11ax_HE20_52T_Low






ANT0, 802.11ax_HE20_52T_Mid






ANT1, 802.11ax_HE20_52T_Mid






ANT0, 802.11ax_HE20_52T_High






ANT1, 802.11ax_HE20_52T_High






ANT0, 802.11ax_HE20_106T_Low



ANT1, 802.11ax_HE20_106T_Low



ANT0, 802.11ax_HE20_106T_High






ANT1, 802.11ax_HE20_106T_High






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (69) / (158) Pages






ANT0, 802.11ax_HE20_242T



ANT1, 802.11ax_HE20_242T



ANT0, 802.11ax_HE40_26T_Low






ANT1, 802.11ax_HE40_26T_Low






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (71) / (158) Pages






ANT0, 802.11ax_HE40_26T_Mid






ANT1, 802.11ax_HE40_26T_Mid






ANT0, 802.11ax_HE40_26T_High






ANT1, 802.11ax_HE40_26T_High






ANT0, 802.11ax_HE40_52T_Low






ANT1, 802.11ax_HE40_52T_Low






ANT0, 802.11ax_HE40_52T_Mid



ANT1, 802.11ax_HE40_52T_Mid



ANT0, 802.11ax_HE40_52T_High






ANT1, 802.11ax_HE40_52T_High






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00950
Page (76) / (158) Pages






ANT0, 802.11ax_HE40_106T_Low



ANT1, 802.11ax_HE40_106T_Low



ANT0, 802.11ax_HE40_106T_Mid






ANT1, 802.11ax_HE40_106T_Mid






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00950
Page (78) / (158) Pages



ANT0, 802.11ax_HE40_106T_High



ANT1, 802.11ax_HE40_106T_High