

11A_Ant1_5720_UNII-3



11A_Ant0_5745



11A_Ant1_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_5785



11A_Ant1_5785



11A_Ant0_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant1_5825



11N20MIMO_Ant0_5180



11N20MIMO_Ant1_5180

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5200



11N20MIMO_Ant1_5200



11N20MIMO_Ant0_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant1_5240



11N20MIMO_Ant0_5260



11N20MIMO_Ant1_5260

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5280



11N20MIMO_Ant1_5280



11N20MIMO_Ant0_5320

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant1_5320



11N20MIMO_Ant0_5500



11N20MIMO_Ant1_5500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5580



11N20MIMO_Ant1_5580



11N20MIMO_Ant0_5700

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant1_5700



11N20MIMO_Ant0_5720_UNII-2C



11N20MIMO_Ant1_5720_UNII-2C

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5720_UNII-3



11N20MIMO_Ant1_5720_UNII-3



11N20MIMO_Ant0_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant1_5745



11N20MIMO_Ant0_5785



11N20MIMO_Ant1_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5825



11N20MIMO_Ant1_5825



11N40MIMO_Ant0_5190

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant1_5190



11N40MIMO_Ant0_5230



11N40MIMO_Ant1_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5270



11N40MIMO_Ant1_5270



11N40MIMO_Ant0_5310

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant1_5310



11N40MIMO_Ant0_5510



11N40MIMO_Ant1_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5550



11N40MIMO_Ant1_5550



11N40MIMO_Ant0_5670

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant1_5670



11N40MIMO_Ant0_5710_UNII-2C



11N40MIMO_Ant1_5710_UNII-2C

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5710_UNII-3



11N40MIMO_Ant1_5710_UNII-3



11N40MIMO_Ant0_5755

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant1_5755



11N40MIMO_Ant0_5795



11N40MIMO_Ant1_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant0_5210



11AC80MIMO_Ant1_5210



11AC80MIMO_Ant0_5290

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant1_5290



11AC80MIMO_Ant0_5530



11AC80MIMO_Ant1_5530

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant0_5610



11AC80MIMO_Ant1_5610



11AC80MIMO_Ant0_5690_UNII-2C

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.