




11AX20 _Ant0_6855




11AX20 _Ant0_6875




11AX20 _Ant0_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20 _Ant0_7115




11AX40 _Ant0_5965




11AX40 _Ant0_6165


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6405




11AX40 _Ant0_6445




11AX40 _Ant0_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6525




11AX40 _Ant0_6565




11AX40 _Ant0_6685


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6845




11AX40 _Ant0_6885




11AX40 _Ant0_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_7085




11AX80 _Ant0_5985




11AX80 _Ant0_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6385




11AX80 _Ant0_6465




11AX80 _Ant0_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6705




11AX80 _Ant0_6785




11AX80 _Ant0_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6945




11AX80 _Ant0_7025




11AX160 _Ant0_6025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant0_6185




11AX160 _Ant0_6345




11AX160 _Ant0_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant0_6665




11AX160 _Ant0_6825




11AX160 _Ant0_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_5955




11BE20 _Ant0_6175




11BE20 _Ant0_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6435




11BE20 _Ant0_6475




11BE20 _Ant0_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6535




11BE20 _Ant0_6715




11BE20 _Ant0_6855


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6875




11BE20 _Ant0_7015




11BE20 _Ant0_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_5965




11BE40 _Ant0_6165




11BE40 _Ant0_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6445




11BE40 _Ant0_6485




11BE40 _Ant0_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6565




11BE40 _Ant0_6725




11BE40 _Ant0_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6885




11BE40 _Ant0_7005




11BE40 _Ant0_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant0_5985



11BE80 _Ant0_6145



11BE80 _Ant0_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.